

Gener 8 Kara G- Thermal Imaging results

Machine ID	Report ID	Page no	Recommendation
No3 Auxiliary engine	Auxiliary engines	11,16 &17	Exhaust leak around Turbocharger gas outlet. Insulation to be renewed
No1 Auxiliary engine	Auxiliary engines	25,27 & 28	Exhaust leak around Turbocharger gas outlet. Insulation to be renewed
No 2 Auxiliary engine	Auxiliary engines	35,37 & 38	Exhaust leak around Turbocharger gas outlet. Insulation to be renewed
No2 Ballast pump control panel	Cargo ,IG system & Boiler panel	150	Delta T is 10 deg at the connection. Clean the terminals and contact. Check the current in all phases after rectifying the fault. Isolate power supply before working on power panels